

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2016-01-22	TECHNICIAN Darren Mann		JOB/ORDER # 5746		REFERENCE TEXT Client reference
FIRST NAME ZANE		LAST NAME MOHAMMED	7		
BILLING ADDRESS COMPANY / BILLING NAME 503 WEST 16TH AVE VANCOUVER, V5Z 4N3 BRITISH COLUMBIA, CANADA		\sim	4	SERVICE ADDRESS 409 - 503 WEST 16TH AVE BUZZER: 321 VANCOUVER, V5Z 4N3 BRITISH COLUMBIA, CANADA	
PHONE 604-719-5772				EMAIL ZANE.MOHAMMED@yahoo.com	m

REASON FOR TODAY'S CALL:

KITCHEN SINK - there is a slow leak from two of the steel braided lines

DESCRIPTION OF WORK PERFORMED:

The faucet was leaking from the connection between the spray head and hose. The leaking appeared to be coming from hairline cracks in the threads of the spray head. I replaced the faucet with a new Delta Palo faucet and tested.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Delta Palo CP - Pull-	CP - Pull-Out INSTALLED				\$319.00
0			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$319.00
Give us Jeedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>				LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER : MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MAD WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLED		GST (5%):	\$15.95
						TOTAL:	\$334.95
		<u>u!</u>	MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2016-01-22				
				CUSTOMER SIGNATURE			