

HST #837181627

DATE	TECHNICIAN		JOB/ORDER #		REFERENCE TEXT	
2016-01-22	Darren Mann		5759		Client reference	
FIRST NAME May		LAST NAME Chow	7			
BILLING ADDRESS COMPANY / BILLING NAME 133 EAST 8TH AVENUE VANCOUVER, V5T1R8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #210 - 133 EAST 8TH AVENUE, BUZZER 7006 VANCOUVER, V5T1R8 BRITISH COLUMBIA, CANADA		
PHONE				EMAIL		
778-929-5694				maybeonline.09@gmail.com		

REASON FOR TODAY'S CALL:

Seal around the kitchen sink drain is breaking down. There is a garburator attached to the drain and the leaking is around the seal under the sink.

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator mounting bracket and tested by filling and draining the sink multiple times while running the garburator.

QTY .	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Garburate	ator Mounting Bracket				\$159.00
Rung of Goodle and			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTE MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M	GST (5%):		\$7.95	
		INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95		
		MATERIALS SETTLED, RI RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAN LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT REAP USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AN FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER E. & O. E.				
		·	CUSTOMER SIGNATURE				