



DATE 2016-02-01	TECHNICIAN Darren Mann	JOB/ORDER # 5785	REFERENCE TEXT Client reference
FIRST NAME Lynden		LAST NAME Wei	
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 605 - 1211 MELVILLE BUZZER: #0605 VANCOUVER, V6E 0A7 BRITISH COLUMBIA, CANADA	
PHONE 778.919.9810		EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:
 Guest bathroom: toilet not flushing fully - could be partial clog | Tank also overfilling *pick up keys from office.

DESCRIPTION OF WORK PERFORMED:
 The toilet fillvalve was not fully shutting the water off when the tank was filled and the flapper was not allowing enough water out of the tank during a flush. I replaced the toilet fillvalve, flapper, and supply line. Tested by flushing large rolled up balls of toilet paper.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Fill-Valve, Flapper, Supply - Standard	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2016-02-01

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45