

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-02-04	TECHNICIAN Darren Mann		JOB/ORDER # 5808	REFERENCE TEXT Client reference		
FIRST NAME Frank		LAST NAME McEvoy				
BILLING ADDRESS COMPANY / BILLING NAME 205 - 1688 ROBSON ST VANCOUVER, V6G1C7 BRITISH COLUMBIA, CANADA			BUZ#2222 VANCOUVER, V6G1C	205 - 1688 ROBSON ST		
PHONE 604.609.2511			EMAIL fpmcevoy@shaw.ca	7		

REASON FOR TODAY'S CALL: garburator jammed

## DESCRIPTION OF WORK PERFORMED:

The garburator was leaking right through the unit, I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE			UNIT PRICE	PRICE		
1	1	Supply & Install 1/2	upply & Install 1/2HP Badger5 Garburator			\$299.00	\$299.00
Run (Teally al		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$299.00	
<b>Give us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 3 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE	GST (5%):		\$14.95		
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$313.95			
invoice and tell us how we did.		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD IPPES, FITXURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. UMAGES S. E. & O. E. CUSTOMER SIGNATURE DATE DATE					