

2016-02-10

DATE

HST #837181627

DATE 2016-02-10	TECHNICIAN Darren Mann	Way.	JOB/ORDER # 5830	REFERENCE TEXT Client reference	
FIRST NAME Jennifer		LAST NAME Cunningham			
BILLING ADDRESS COMPANY / BILLING NAME 1133 HOMER ST VANCOUVER, V6B 0B1 BRITISH COLUMBIA, CANADA			SERVICE ADDRE #PH2 - 1133 HOM VANCOUVER, V6 BRITISH COLUMB	IER ST, BUZZER 2201 B 0B1	
PHONE 6047878929			EMAIL jenrencunningham	ı@icloud.com	

REASON FOR TODAY'S CALL:

master bathroom shower cartridge leaking.

DESCRIPTION OF WORK PERFORMED:

I replaced the master bathroom shower valve mixing cartridge and tested.

Treplaced the master bathloom shower valve mixing cartiloge and tested.								
QTY.	CODE		UNIT PRICE	PRICE				
1		Replace Shower VLV Mixing Cartridge - American Standard			\$159.00			
<i>Q</i>	(I	and hack w	Y: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95			
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95			
		ve did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					

CUSTOMER SIGNATURE