



DATE 2016-02-11	TECHNICIAN Darren Mann	JOB/ORDER # 5835	REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 302 - 238 ALVIN NAROD MEWS ZEE: 604.618.4081 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100		EMAIL vera@rentitfurnished.com	

REASON FOR TODAY'S CALL:
 toilet tank cracked *Centre of Cap to the wall 12 inches Bottom of counter to the floor 29. 7/8 inches

DESCRIPTION OF WORK PERFORMED:
 The toilet tank was cracked. Crane is no longer in business and a replacement tank could not be ordered. I delivered and installed a new Kohler toilet and disposed of the old.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Kohler Toilet - Wellworth	\$265.00	\$265.00
2		Labour	\$99.00	\$198.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$463.00
GST (5%):	\$23.15
TOTAL:	\$486.15

_____ 2016-02-11

 CUSTOMER SIGNATURE DATE