



DATE 2016-02-12	TECHNICIAN Darren Mann	JOB/ORDER # 5833	REFERENCE TEXT Client reference
FIRST NAME Angela		LAST NAME Cheng	
BILLING ADDRESS COMPANY / BILLING NAME 628 WEST 13 AVE VANCOUVER, V5Z1N9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #310 - 628 WEST 13 AVE, BUZZER 628 VANCOUVER, V5Z1N9 BRITISH COLUMBIA, CANADA	
PHONE 778-960-7327		EMAIL angelacheng44@gmail.com	

REASON FOR TODAY'S CALL:

The right sink is leaking (first picture), the top part which had been attached on to the sink is no longer secured on, unlike the second picture which is in place and sturdy.

DESCRIPTION OF WORK PERFORMED:

I replaced the right sink basket strainer assembly and tested by filling and draining both sides of the sink.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Basket Strainer	\$149.00	\$149.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$149.00
GST (5%):		\$7.45
TOTAL:		\$156.45

 <hr/> CUSTOMER SIGNATURE	2016-02-12 <hr/> DATE
--	--------------------------