



2016-03-01

HST #837181627

DATE 2016-03-01	TECHNICIAN Darren Mann		JOB/ORDER # 5905		REFERENCE TEXT 16-0301	
FIRST NAME Advent		LAST NAME Admin	97			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 508 - 688 ABBOTT ST GEORGE: 778.968.0990 BUZ#243 VANCOUVER, BRITISH COLUMBIA, CANADA	Α	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	1	

REASON FOR TODAY'S CALL:

Garburator not working.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber was badly deteriorated and there was a crack in the drain 90. I replaced the garburator and drain 90 with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION			
1	1	Supply & Install 1/2	\$279.00	\$279.00		
Gwe us Feedback Please visit our feedback page at:		Soud and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95			
Thank You!			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			