

HST #837181627

DATE 2016-03-16	TECHNICIAN Darren Mann		JOB/ORDER # 5950	REFERENCE TEXT Client reference		
FIRST NAME Jamie		LAST NAME Johnston				
BILLING ADDRESS COMPANY / BILLING NAME 703 - 1005 BEACH AVE VANCOUVER BC, V6E 3W2 BRITISH COLUMBIA, CANADA		703 - 1005 BEA BUZZER: 1133 VANCOUVER	SERVICE ADDRESS 703 - 1005 BEACH AVE BUZZER: 1133 VANCOUVER BC, V6E 3W2 BRITISH COLUMBIA, CANADA			
PHONE 604.868.0619			EMAIL Jamesajohnsto	EMAIL Jamesajohnston@shaw.ca		

REASON FOR TODAY'S CALL:

The garburator is leaking

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking through cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Badger5 Garburator			\$309.00
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$309.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE