

(E) @SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2016-04-18	TECHNICIAN Darren Mann		JOB/ORDER # 6058		REFERENCE TEXT Client reference
FIRST NAME Marko		LAST NAME Kerkez	7		
BILLING ADDRESS COMPANY / BILLING NAME 906 - 1420 WEST GEORGIA ST VANCOUVER, V6G3K4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #906 - 1420 WEST GEORGIA S VANCOUVER, V6G3K4 BRITISH COLUMBIA, CANADA	
PHONE 778-772-2421				EMAIL kerkez@yahoo.com	

REASON FOR TODAY'S CALL:

-garburator fell off of mounting -low water pressure in kitchen faucet

## DESCRIPTION OF WORK PERFORMED:

-The garburator came loose from the mount. I re-secured it to the mount and tested. -I was informed while onsite the kitchen faucet was not well secured to the countertop. I removed the spray hose to better gain access to the securing nuts, tightened the nuts, and re-installed the spray hose. -The issue with low pressure in the kitchen faucet seems to be within the spray head. Unfortunately I do not have the key required to remove the aerator.

QTY.	CODE	DESCRIPTION					PRICE
1		Labour	×			\$109.00	\$109.00
<b>Gwe us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>	and a al	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$109.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$5.45		
				TOTAL:	\$114.45		
	<u>u!</u>	SETTLED, RU RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RE STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MAT & O. E.				
			I		2016-04-18		
				CUSTOMER SIGNATURE	DATE		