



DATE 2016-04-26	TECHNICIAN Darren Mann	JOB/ORDER # 6075	REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME McLellan	
BILLING ADDRESS COMPANY / BILLING NAME 1201 - 120 MILROSS AVE VANCOUVER, V6A 4K7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1201 - 120 MILROSS AVE, BUZZER 074 VANCOUVER, V6A 4K7 BRITISH COLUMBIA, CANADA	
PHONE 604.355.0033		EMAIL mclellandjvcr@shaw.ca	

REASON FOR TODAY'S CALL:  
 My Badger 5 garburator is not working - engaging power, nothing happens. It is about 13 years old. It needs either repair or replacement.

DESCRIPTION OF WORK PERFORMED:  
 -The garburator had cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$309.00
GST (5%):	\$15.45
TOTAL:	\$324.45

  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2016-04-26  
 \_\_\_\_\_  
 DATE