



DATE 2016-05-03	TECHNICIAN Darren Mann	JOB/ORDER # 6110	REFERENCE TEXT Client reference
FIRST NAME Farouk		LAST NAME Ratansi	
BILLING ADDRESS COMPANY / BILLING NAME 1102 - 1003 BURNABY ST VANCOUVER, V6E4R7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1102 - 1003 BURNABY ST BUZZER 2018 VANCOUVER, V6E4R7 BRITISH COLUMBIA, CANADA	
PHONE 604.619.6652		EMAIL Fratansi@cutrust.com	

REASON FOR TODAY'S CALL:
 -tub faucet won't turn off(Supergrif) -garburator not working

DESCRIPTION OF WORK PERFORMED:
 -I replaced the shower valve cartridge and tested. -I unjammed the garburator by removing a layer of rust. Tested by filling and draining the sink while running the garburator. The garburator leaks from the connection between the garburator and the mounting bracket. I suggested replacing the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$199.00	\$199.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$199.00
 GST (5%): \$9.95
 TOTAL: \$208.95



2016-05-03

CUSTOMER SIGNATURE DATE