

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-05-04	TECHNICIAN Darren Mann		JOB/ORDER # 6119		REFERENCE TEXT Client reference	
FIRST NAME Julia		LAST NAME Kim	7			
BILLING ADDRESS COMPANY / BILLING NAME 1205 - 161 WEST GEORGIA STREET VANCOUVER, V6B0K9 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 713 - 1325 ROLSTON STREET VANCOUVER, V6B 0M2 BRITISH COLUMBIA, CANADA		
PHONE 604.418.1060				EMAIL julia786@yahoo.ca		

REASON FOR TODAY'S CALL:

The bath faucet seems to have separated from the wall and there is now a gap

## DESCRIPTION OF WORK PERFORMED:

-The spout came detached from the wall. I removd the spout, siliconed around the copper coming out of the wall, and re-installed the spout. Tested and in good working order.

QTY.	CODE		DESCRIPTION				PRICE
1		Discount Labour	1			\$99.00	\$99.00
Guve us Geedback   Please visit our feedback page at:   www.yaletownplumbing.com/feedback   [1]   Fill in the required details from your   invoice and tell us how we did.   Thank You!		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$99.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO			GST (5%):	\$4.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95		
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <b>TERMS</b> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2016-05-04					
		CUSTOMER SIGNATURE DATE					