



HST #837181627

DATE 2016-05-10	TECHNICIAN Darren Mann		JOB/ORDER # 6142		REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  307 - 289 DAKE ST ANGELINE: 604.754.2001 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100				EMAIL vera@rentitfurnished.com	

## REASON FOR TODAY'S CALL:

Kitchen faucet leaking.

## DESCRIPTION OF WORK PERFORMED:

-The kitchen faucet was not only leaking to the cabinet below but the threads securing the faucet to the counter were broken. The Hot shut off valve under the kitchen sink was not working, I repaired this valve by replacing the washer, stem, packing, packing nut, and handle. I then replaced the kitchen faucet with a new Delta Palo and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1	//	Delta Palo CP - Pull-Out INSTALLED			\$329.00
1		Repair 1/2" x 3/8" Angle or Straight Stop - ADD-ON			\$25.00
Please visit our feedback page at:		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$354.00
				GST (5%):	\$17.70
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$371.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT	IS HEREBY
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES	AND
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR	R BROKEN,
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHE	R DAMAGES
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TR	UCK
CHARGES. E. & O. E.	

2016-05-10 CUSTOMER SIGNATURE DATE