

(a) @SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2016-05-27	TECHNICIAN Darren Mann		JOB/ORDER # 6185		REFERENCE TEXT Client reference
FIRST NAME Thomas L		LAST NAME Novak	7		
BILLING ADDRESS COMPANY / BILLING NAME 1402 - 989 BEATTY ST VANCOUVER, V6Z3C2 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 1402 - 989 BEATTY STREET BUZZER: 2402 VANCOUVER, V6Z3C2 BRITISH COLUMBIA, CANADA		
PHONE 778.233.4120				EMAIL tomnovak@telus.net	

REASON FOR TODAY'S CALL:

Garburator no longer functions likely requires replacement as it appears to be a cheap piece of junk!

## DESCRIPTION OF WORK PERFORMED:

I unjammed the garburator and tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION				UNIT PRICE	PRICE
1	/	Labour	7			\$109.00	\$109.00
0		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$109.00
<b>Give us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your		L	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTI MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M		GST (5%):	\$5.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOV	TOTAL:	\$114.45		
<u>Thar</u>	<u>ık Yoı</u>	<u></u>	SETTLED, RU RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A room CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE & O. E. CUSTOMER SIGNATURE	AND ANY OTHER DAMAGES		