

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-05-27	TECHNICIAN Darren Mann		JOB/ORDER # 6184		REFERENCE TEXT Client reference
FIRST NAME Agata		LAST NAME Burdziuk	7		
BILLING ADDRESS COMPANY / BILLING NAME 1295 RICHARDS ST VANCOUVER, V6B 6M6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #708 - 1295 RICHARDS ST BU JONATHAN(TENANT): 778.681 VANCOUVER, V6B 6M6 BRITISH COLUMBIA, CANADA	.8564
PHONE 6043072656	-			EMAIL burdziuk@hotmail.com	

REASON FOR TODAY'S CALL:

Garburator isn't working ... making a low sounding hum ... most likely needs replacement Standard sink ** give 15 minute heads up**

DESCRIPTION OF WORK PERFORMED:

The garburator had cracks in the housing and the grinding chamber was seized up. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE			DESCRIPTION		PRICE	
1		Supply & Install 1/2	bly & Install 1/2HP Badger5 Garburator				\$309.00
Cure of Goodle al			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WA	SUBTOTAL:	\$309.00	
Give us Feedback Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSC			GST (5%):	\$15.45	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATE	TOTAL:	\$324.45			
invoice and tell us how we did. <u>Thank You!</u>		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E. 2016-05-27					
				CUSTOMER SIGNATURE	DATE		
						_	