



2016-06-06

DATE

HST #837181627

DATE 2016-06-06	TECHNICIAN Darren Mann		JOB/O 6207	RDER #	REFERENCE TEXT Client reference
FIRST NAME Jenn		LAST NAME Kirker			
BILLING ADDRESS COMPANY / BILLING NAME 3847 W 30TH AVE VANCOUVER, V6S 1W9 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 3847 W 30TH AVE VANCOUVER, V6S 1W9 BRITISH COLUMBIA, CANADA	
PHONE 6047621063				EMAIL jennkirker@gmail.com	

REASON FOR TODAY'S CALL:

Toilet not flushing properly. The "flapper" (?) or cap in the tank is broken and won't reseal properly after each flush.

DESCRIPTION OF WORK PERFORMED:

The flapper was breaking down and one of the connecting arms had broken. I replaced the flapper with a new 3" Fluidmaster adjustable flapper and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1	У	Replace Toilet Flapper	- 3"	\$139.00	\$139.00
Ruse	, 115 G	eodhach war	REANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
	Gwe us Feedback Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.9
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.9
		we did.	ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. ERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK HARGES. E. & O. E.		

CUSTOMER SIGNATURE