



HST #837181627

DATE 2016-06-15	TECHNICIAN Darren Mann		JOB/ORDER # 6238	REFERENCE TEXT 16-0790	
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			301 - 2388 WEST NADIA: 778.288.: VANCOUVER,	SERVICE ADDRESS  301 - 2388 WESTERN PARKWAY NADIA: 778.288.2789 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478			EMAIL andrea@adventv	ancouver.com	

REASON FOR TODAY'S CALL:

Shower spray head holder broken. \*778.682.2589

## DESCRIPTION OF WORK PERFORMED:

-I replaced the broken handshower bracket and tested.

QTY.	CODE	DESCRIPTION			PRICE
1		Discount Labour		\$99.00	\$99.00
1	75	LSHSB-CP HandSho	ower Bracket	\$20.00	\$20.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$119.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$124.95

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES. E. & O. E. 2016-06-15 CUSTOMER SIGNATURE