



HST #837181627

DATE 2016-06-16	TECHNICIAN Darren Mann		JOB/ORDER # 6246		REFERENCE TEXT Client reference			
FIRST NAME Robert		LAST NAME Daum	97					
BILLING ADDRESS COMPANY / BILLING NAME 401 - 1236 BIDWELL ST VANCOUVER, V6G2K9 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 401 - 1236 BIDWELL ST, BUZZ VANCOUVER, V6G2K9 BRITISH COLUMBIA, CANADA				
PHONE 778.987.2918				EMAIL robertdaum@gmail.com				

REASON FOR TODAY'S CALL:

leak under kitchen sink

DESCRIPTION OF WORK PERFORMED:

The garburator mounting bracket worked its way loose and water was seeping out of the connection between the garburator and the mount that attaches to the sink. I tightened this bracket and tested by filling the sink 6" and draining multiple times while running the garburator

TECHNICIAN RECOMMENDATIONS:

I recommended searching for a battery powered water sensor alarm to keep in the cabinet.

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$109.00	\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		RANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
		s from your		TOTAL:	\$114.45

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-06-16

CUSTOMER SIGNATURE

DATE