



DATE 2016-06-24	TECHNICIAN Darren Mann	JOB/ORDER # 6258	REFERENCE TEXT Client reference
FIRST NAME Jennifer		LAST NAME Sun	
BILLING ADDRESS COMPANY / BILLING NAME 601 - 907 BEACH AVE VANCOUVER, V6Z 2R3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 601 - 907 BEACH AVENUE BUZZER: 601 VANCOUVER, V6Z 2R3 BRITISH COLUMBIA, CANADA	
PHONE 604.805.6283		EMAIL jen910805@hotmail.com	

REASON FOR TODAY'S CALL:
Garburator is leaking

DESCRIPTION OF WORK PERFORMED:
-The garburator was leaking right through the bottom of the housing. I replaced the garburator with a new Badger5 and tested by filling draining both sides of the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-06-24

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$309.00
GST (5%):	\$15.45
TOTAL:	\$324.45