



DATE 2016-06-28	TECHNICIAN Darren Mann	JOB/ORDER # 6260	REFERENCE TEXT Client reference
FIRST NAME James		LAST NAME Lin	
BILLING ADDRESS COMPANY / BILLING NAME 4008 - 1408 STRATHMORE MEWS VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 4008 - 1408 STRATHMORE MEWS BUZZER: #1282 VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA	
PHONE 604.562.6364		EMAIL linjames_abc@yahoo.com	

REASON FOR TODAY'S CALL:
 Slow leak of the hot water valve (left valve in the photo) under the washroom sink.

DESCRIPTION OF WORK PERFORMED:
 There was water leaking from the stem of the Hot water shut off valve located under the master bathroom lavatory sink. I repaired this valve, as well as the Cold valve next to it, by replacing the washers, stems, packing, packing nuts, and handles.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00
1		Repair 1/2" x 3/8" Angle or Straight Stop - ADD-ON	\$25.00	\$25.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-06-28

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$164.00
GST (5%):	\$8.20
TOTAL:	\$172.20