

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2016-06-28	TECHNICIAN Darren Mann		JOB/ORDER # 6269		REFERENCE TEXT Client reference
FIRST NAME Joan		LAST NAME McLellan			
BILLING ADDRESS				SERVICE ADDRESS	
902 - 821 CAMBIE ST VANCOUVER, V6B0E3 BRITISH COLUMBIA, CANADA				902 - 821 CAMBIE, BUZ5050 CALL JULIE FOR ENTRY: 1.230 VANCOUVER, V6B0E3 BRITISH COLUMBIA, CANADA	
PHONE 250-540-8031				EMAIL JOANMCLELLAN100@gmail.cc	om

REASON FOR TODAY'S CALL: Running toilet(Caroma)

DESCRIPTION OF WORK PERFORMED:

I replaced the flushvalve gaskets in both toilets. Tested and in good working order.

QTY.	CODE		DESCRIPTION		
1	//	Replace FlushValve Gasket - Caroma			\$139.00
1	//	Replace Additional FlushValve Gasket - Caroma			\$29.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$168.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LA	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$8.40
		com/feedback [1]			\$176.40

Thank You!

invoice and tell us how we did.

WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	
INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE CHARGES. E. & O. E.	AT CHARGES AND PONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES
	2016-06-28
CUSTOMER SIGNATURE	DATE
COCTOMEN CICION TONE	57112