

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2016-07-14	TECHNICIAN Darren Mann		JOB/ORDER # 6330		REFERENCE TEXT Client reference
FIRST NAME Paul		LAST NAME Rosenau	97		
BILLING ADDRESS COMPANY / BILLING NAME 3306 WEST 11TH AVE VANCOUVER, BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 304 - 1228 HOMER ST, BUZ#1 ^o KEVIN: 604.220.4106 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.739.7526				EMAIL Rosenau@ekistics.ca	

REASON FOR TODAY'S CALL:

Garburator not working.

DESCRIPTION OF WORK PERFORMED:

The inside of the garburator grinding chamber had deteriorated and the housing had a crack in it. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Badger5 Garburator			\$309.00
Para Candland			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00
Gwe us Feedback Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45
invoice and tell us how we did. Thank You!			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE