

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2016-07-18	TECHNICIAN Darren Mann		JOB/ORDER # 6336		REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 408 - 1275 HAMILTON ST GRAB KEYS FROM OFFICE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100				EMAIL vera@rentitfurnished.com	

REASON FOR TODAY'S CALL: garburator jammed

DESCRIPTION OF WORK PERFORMED:

The inside of the garburator grinding chamber was completely rusted out. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$15.45
			TOTAL:	\$324.45
		We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE

DATE