

HST #837181627

DATE 2016-07-25	TECHNICIAN Darren Mann		JOB/ORDER # 6340		REFERENCE TEXT Client reference
FIRST NAME Dustin		LAST NAME Jones	7		
BILLING ADDRESS COMPANY / BILLING NAME 609 - 822 SEYMOUR ST VANCOUVER, V6B 1L7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 609 - 822 SEYMOUR VANCOUVER, V6B 1L7 BRITISH COLUMBIA, CANADA	
PHONE 604.619.3041				EMAIL d92jones@gmail.com	

REASON FOR TODAY'S CALL:

Garbage disposal is not working, does not rotate...and clogs up the sink...and water sits and drains slowly in the sink when used.

DESCRIPTION OF WORK PERFORMED:

-The garburator had a crack in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION			
1		Supply & Install 1/2H	P Badger5 Garburator	\$309.00	\$309.00	
Gwe us Feedback WARRANTY:			RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45	
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45	
			AADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2016-07-25			
			CUSTOMER SIGNATURE DATE			