



DATE 2016-07-28	TECHNICIAN Darren Mann	JOB/ORDER # 6337	REFERENCE TEXT Client reference
FIRST NAME Patti		LAST NAME Caldwell	
BILLING ADDRESS COMPANY / BILLING NAME 1103 - 1408 STRATHMORE MEWS VANCOUVER, V6Z3A9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1103 - 1408 STRATHMORE MEWS VANCOUVER, V6Z3A9 BRITISH COLUMBIA, CANADA	
PHONE 604.341.5443		EMAIL patti@patticaldwell.com	

REASON FOR TODAY'S CALL:
 -garburator not working -kitchen faucet head leaking

DESCRIPTION OF WORK PERFORMED:
 -I replaced the garburator with a new Badger5 and tested. -I installed a new Grohe kitchen faucet spray head and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00
1		Grohe 46298IEO SPRY HEAD	\$140.00	\$140.00
SUBTOTAL:				\$449.00
GST (5%):				\$22.45
TOTAL:				\$471.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 CUSTOMER SIGNATURE

2016-07-28

 DATE