

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-07-29	TECHNICIAN Darren Mann		JOB/O 6360	RDER #	REFERENCE TEXT Client reference
FIRST NAME Neil		LAST NAME Malik			
BILLING ADDRESS COMPANY / BILLING NAME 410 - 909 MAINLAND ST VANCOUVER, V6B1S3 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 410 - 909 MAINLAND ST, BUZZ VANCOUVER, V6B1S3 BRITISH COLUMBIA, CANADA	
PHONE 604.562.5481				EMAIL neil.malik@gmail.com	

REASON FOR TODAY'S CALL: Leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:

The garburator drain 90 was cracked. I replaced the drain 90 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION			
1		Replace Garburator Drain 90			\$129.00	
Gwe us Feedback			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$135.45	
		<u>u!</u>	MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			
			CUSTOMER SIGNATURE DATE			