

2016-08-02

HST #837181627

DATE 2016-08-02	TECHNICIAN Darren Mann		JOB/ORDER # 6362	REFERENCE TEXT Client reference	
FIRST NAME Michael		LAST NAME Wach			
BILLING ADDRESS COMPANY / BILLING NAME 906 - 125 MILROSS AVE VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  906 - 125 MILROSS AVE BUZZER: 0906 VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA		
PHONE 778.895.7911			EMAIL michael.wach@tower	rswatson.com	

## REASON FOR TODAY'S CALL:

Leaking garburator. We purchased our condo last fall and observed that garburator had a crack on the outside which had been filled with glue(?). It has given way and is now leaking such that we cannot use the right hand side of the kitchen sink. zero issues with the plumbing associated with the left hand side of the kitchen sink.

## DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION			PRICE
1	//	Supply & Install 1/2	HP Badger5	Garburator	\$309.00	\$309.00
0	Gwe us Feedback WARRANTY:		WARRANTY:	TY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$309.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		GST (5%):	\$15.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl		TOTAL:			\$324.45	
		MADE THAT S MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE