

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-08-02	TECHNICIAN Darren Mann		JOB/ORDER # 6369		REFERENCE TEXT Client reference
FIRST NAME Laura-Lee		LAST NAME Armstrong	7		
BILLING ADDRESS COMPANY / BILLING NAME #902 - 628 KINGHORNE MEWS VANCOUVER, BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #902 - 628 KINGHORNE MEWS VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.644.0781				EMAIL llarmstrong@agroup.ca	

REASON FOR TODAY'S CALL: garburator jammed.

DESCRIPTION OF WORK PERFORMED:

I unjammed the garburator and tested by filling the sink 6" and draining while running the garburator. I did not find anything out of the ordinary inside the grinding chamber, whatever caused the blockage was pushed through.

QTY .	CODE	DESCRIPTION					PRICE
1	1	Labour	7			\$109.00	\$109.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		SUBTOTAL:	\$109.00	
					GST (5%):	\$5.45	
		INTEREST AT		EDGEMENT IS HEREBY	TOTAL:	\$114.45	
	TI IIII IIIIIIIIIIIIIIIIIIIIIIIIIIIIII		RVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND TED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ON CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. SH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK O.E. 2016-08-02 CUSTOMER SIGNATURE DATE				