



DATE 2016-08-05	TECHNICIAN Darren Mann	JOB/ORDER # 6363	REFERENCE TEXT Client reference
FIRST NAME Mary		LAST NAME George	
BILLING ADDRESS COMPANY / BILLING NAME 1506 - 1055 HOMER ST VANCOUVER, V6B1G3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1506 - 1055 HOMER ST BUZZER: 1617 VANCOUVER, V6B1G3 BRITISH COLUMBIA, CANADA	
PHONE 604.779.9126		EMAIL maryhgeorge@gmail.com	

REASON FOR TODAY'S CALL:  
Garburator is leaking


DESCRIPTION OF WORK PERFORMED:  
The garburator was leaking through a crack in the housing. I replaced the garburator with a new Badger5 and tested by filling both sinks half way and draining multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY  
**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2016-08-05  
 \_\_\_\_\_  
 DATE

SUBTOTAL:	\$309.00
GST (5%):	\$15.45
TOTAL:	\$324.45