

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE	TECHNICIAN		JOB/ORDER #	REFERENCE TEXT	
2016-08-05	Darren Mann		6380	Client reference	
FIRST NAME Mike		LAST NAME Drew			
BILLING ADDRESS			SERVICE ADDRESS		
COMPANY / BILLING NAME			2301 - 1495 RICHARDS ST		
#2301 - 1495 RICHARDS ST			BUZZER: 1155		
VANCOUVER, V6Z3E3			VANCOUVER, V6Z3E3		
BRITISH COLUMBIA, CANADA			BRITISH COLUMBIA, CANADA		
PHONE			EMAIL	EMAIL	
604.616.0112			mikedrew_12@hotmail	mikedrew_12@hotmail.com	

REASON FOR TODAY'S CALL:

my 'in sink erator' garberator leaks out of the bottom.

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	1	Supply & Install 1/2HP Badger5 Garburator			\$309.00
Guve us Jeedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>		and a du	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45
		<u>u!</u>	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORARTION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		