

HST #837181627

DATE 2016-08-23	TECHNICIAN Darren Mann		JOB/ORDER # 6424		REFERENCE TEXT Client reference	
FIRST NAME wally		LAST NAME nagamatsu	707			
BILLING ADDRESS COMPANY / BILLING NAME 1807 - 1775 QUEBEC ST VANCOUVER, V5T 0E3 BRITISH COLUMBIA, CANADA			14	SERVICE ADDRESS 1807 - 1775 QUEBEC STREET VANCOUVER, V5T 0E3 BRITISH COLUMBIA, CANADA		
PHONE 604.655.9596				EMAIL wnagamatsu@shaw.ca		

REASON FOR TODAY'S CALL: have a running toilet (Kohler)

DESCRIPTION OF WORK PERFORMED:

-I removed the cap of the FillValve and found a small piece of debris stuck the diaphram. I removed the debris, re-installed the cap, and tested. -The owner inquired how this was done so he could do it in the future if necessary, I showed him step by step. -After testing we noticed a slight hiss had returned. I replaced the mechanical portion of the FillValve and tested again.

QTY.	CODE	DESCRIPTION				PRICE
1		Replace toilet FillValve - standard				\$149.00
		/ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$149.00	
				GST (5%):	\$7.45	
		-/10.01	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45	
			THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE

DATE