

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-08-30	TECHNICIAN Darren Mann		JOB/ORDER # 6444		REFERENCE TEXT Client reference
FIRST NAME Alice		LAST NAME Jia	7		
BILLING ADDRESS COMPANY / BILLING NAME 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA	
PHONE 778.986.7634				EMAIL weiting27@icloud.com	

REASON FOR TODAY'S CALL:

The master bathroom sink stop did not work and there is a leak in the faucet

## DESCRIPTION OF WORK PERFORMED:

-I was able to re-attach the drain stopper and tested by filling and draining the sink multiple times. -I used Teflon tape to seal the threads on the leaking lavatory faucet and tested by running both Hot & Cold on full for a minute. No leaks present.

QTY.	CODE	DESCRIPTION				PRICE
1		Labour	7		\$109.00	\$109.00
0		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
Give us Geedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45	
		MATERIALS I SETTLED, RU RESULTING I	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK . & O. E. CUSTOMER SIGNATURE DETERIOR OF DETERIORO			