

(B) @SimplyPlumbing | | YaletownPlumbing

2016-08-31

HST #837181627

DATE 2016-08-31	TECHNICIAN Darren Mann		JOB/ORDER # 6453	REFERENCE TEXT Client reference	
FIRST NAME Amy		LAST NAME Cho			
BILLING ADDRESS COMPANY / BILLING NAME 313 - 3478 WESBROOK MALL VANCOUVER, V6S0B6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  313 - 3478 WESBROOK MALL BUZZER: 043 VANCOUVER, V6S0B6 BRITISH COLUMBIA, CANADA		
PHONE 778.554.1110			EMAIL hejingel2@gmail.com	) /	

## REASON FOR TODAY'S CALL:

Master Bathroom: The water in the toilet seems to be leaking, as we can hear the water dropping in the bowl every second. The toilet keeps running water into the bowl.

## DESCRIPTION OF WORK PERFORMED:

Small bubbles had formed on the flushvalve gasket. The owner decided to replace the FillValve at the same time given the fact that the other one had been replaced

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Replace Toilet FillV	alve, Flappe	er, Supply - Standard	\$169.00	\$169.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT				PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$8.45	
				TOTAL:	\$177.45	
		MADE THAT S MATERIALS L SETTLED, RU RESULTING F	THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK & O. E.			

CUSTOMER SIGNATURE