

HST #837181627

DATE 2016-09-06	TECHNICIAN Darren Mann		JOB/ORDER # 6462		REFERENCE TEXT 16-1213
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 501 - 1887 CROWE ST KEYS AT OFFICE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478			EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL: garburator not working.

DESCRIPTION OF WORK PERFORMED:

The garburator was seized due to rust buildup, I was able to free it up but during testing noticed that it was also leaking. I replaced the garburator with a new Waste King 1001 and tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Waste King 1001 Garburator			\$279.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY					\$279.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE