

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2016-09-09	TECHNICIAN Darren Mann		JOB/ORDER # 6467		REFERENCE TEXT Client reference
FIRST NAME Rachel		LAST NAME Morisette			
BILLING ADDRESS COMPANY / BILLING NAME 204 - 1924 COMOX ST VANCOUVER, V6G 1R4 BRITISH COLUMBIA, CANADA		- 19		SERVICE ADDRESS 204 - 1924 COMOX STREET VANCOUVER, V6G 1R4 BRITISH COLUMBIA, CANADA	
PHONE 604.244.3292				EMAIL steverachel@gmail.com	

REASON FOR TODAY'S CALL:

Our toilet is continuously trickling water into the bowl like our flush valve has a leak.

DESCRIPTION OF WORK PERFORMED:

-I replaced the flushvalve gasket and rinsed out the FillValve diaphram. Tested and in good working order.

QTY.	CODE		DESCRIPTION			
1	17/	Replace FlushValve Ga	asket - Geberit In-Wall	\$159.00	\$159.00	
0		wari	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95	
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95	
			ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

> 2016-09-09 CUSTOMER SIGNATURE DATE