

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-09-15	TECHNICIAN Darren Mann		JOB/ORDER # 6506		REFERENCE TEXT Client reference
FIRST NAME Rita		LAST NAME Keeler	7		
BILLING ADDRESS COMPANY / BILLING NAME 501 - 1790 BAYSHORE DR VANCOUVER, V6G 3G4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 501 - 1790 BAYSHORE DR VANCOUVER, V6G 3G4 BRITISH COLUMBIA, CANADA	
PHONE 604.266.1414				EMAIL keelerrio@shaw.ca	

REASON FOR TODAY'S CALL:

I need 2 shower heads to be replaced. The bar has been installed. *call mobile for entry: 604-505-2948

DESCRIPTION OF WORK PERFORMED:

-I installed the new shower spray hose and head in the guest bathroom and tested. -After removing the shower head and brass nipple from the master bathroom shower I noticed that the wingback 90 behind the tile is cracked. Unfortunately this will have to be replaced before the new spray hose and head can be installed.

TECHNICIAN RECOMMENDATIONS:

I suggested calling Montalbano for the replacement of the fitting in the master bathroom shower as we are currently only able to take on short service calls. (Montalbano Plumbing: 604.444.0222)

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Install Shower Spray Hose & Head	\$129.00	\$129.00
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Guve us Jeedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.45
			TOTAL:	\$135.45
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SESTILED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAINING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2016-09-15		
		CUSTOMER SIGNATURE DATE		