

HST #837181627

DATE 2016-09-21	TECHNICIAN Darren Mann		JOB/ORDER # 6515	REFERENCE TEXT Client reference	
		LAST NAME DE LA VINA			
BILLING ADDRESS COMPANY / BILLING NAME 320 - 1088 RICHARDS ST VANCOUVER, V6B 0J8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 320 - 1088 RICHARDS ST BUZZER: 5065 VANCOUVER, V6B 0J8 BRITISH COLUMBIA, CANADA			
PHONE 1.236.985.1885		EMAIL MARIAJORBA_90@HC	EMAIL MARIAJORBA_90@HOTMAIL.COM		

REASON FOR TODAY'S CALL: Clogged bathtub

DESCRIPTION OF WORK PERFORMED:

-I used the PowerSpin drain snake to clear hair from the tub drain and tested by filling the tub 8" and draining.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using Powe	\$149.00	\$149.00	
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACT			RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1]			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
			ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY IADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-09-21

CUSTOMER SIGNATURE

DATE