

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2016-09-21	TECHNICIAN Darren Mann		JOB/ORDER # 6524		REFERENCE TEXT Client reference
FIRST NAME Brian		LAST NAME O'neill			
BILLING ADDRESS COMPANY / BILLING NAME 501 - 1010 BURNABY ST VANCOUVER, V6E4L8 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 501 - 1010 BURNABY ST BUZZER: #119 VANCOUVER, V6E4L8 BRITISH COLUMBIA, CANADA	
PHONE 604.331.2366				EMAIL bjoneill@shaw.ca	

REASON FOR TODAY'S CALL:

The Insinkerator - Badgre 5 is leaking ... just a little ...

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking right through the unit. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running

g					
QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2	\$309.00	\$309.00	
0		and a du	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$324.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE