

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-09-23	TECHNICIAN Darren Mann		JOB/O 6521	RDER #	REFERENCE TEXT Client reference
FIRST NAME Maria		LAST NAME Lopez	7		
BILLING ADDRESS COMPANY / BILLING NAME 304 - 1088 WEST 14TH AVE VANCOUVER, V6H0A6 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 304 - 1088 WEST 14TH AVE, BUZZER N/A VANCOUVER, V6H0A6 BRITISH COLUMBIA, CANADA		
PHONE 778.318.3980				EMAIL Maria_elena_lopez@hotmail.com	

REASON FOR TODAY'S CALL:

The Badger 5 Insinkerator is leaking from the bottom, when it is in use and also when only the sink is running. How much to replace the unit with an identical model?

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining both sides of the sink while running the garburator.

<b>QTY</b> .	CODE		DESCRIPTION					
1		Supply & Install 1/2	bly & Install 1/2HP Badger5 Garburator					
0	a	and a al	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00			
<b>Gwe us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45			
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45			
<u>Tha</u>	<u>nk You</u>	<u>u!</u>	MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					
		2016-09-23						
			CÜSTOMER SIGNATURE DATE					