

HST #837181627

DATE 2016-09-27	TECHNICIAN Darren Mann		JOB/ORDER # 6474	REFERENCE TEXT Client reference	
FIRST NAME Fred		LAST NAME Taylor			
BILLING ADDRESS COMPANY / BILLING NAME 1935 HARO STREET VANCOUVER, V6G 1H8 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  303 - 1935 HARO STREET BUZZER: 009 VANCOUVER, V6G 1H8 BRITISH COLUMBIA, CANADA		
PHONE 6046894866			EMAIL fredht@telus.net		

## REASON FOR TODAY'S CALL:

I have a Kohler Toilet with a flushmate system. I have ordered the replacement for the flushmate system which should be here for installation with instructions prior to the requested date. (the current flushmate vessel has a pin hole leaks)

## DESCRIPTION OF WORK PERFORMED:

I installed the new Kohler Flushmate tank and tested.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Instal Kohler Flush	mate Tank		\$189.00	\$189.00
		WARRANTY:	LANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$189.00	
				GST (5%):	\$9.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$198.45	
			EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

DATE

CUSTOMER SIGNATURE