



DATE 2016-09-28	TECHNICIAN Darren Mann	JOB/ORDER # 6554	REFERENCE TEXT Client reference
FIRST NAME Maxine		LAST NAME Jakubke	
BILLING ADDRESS COMPANY / BILLING NAME 406 - 969 RICHARDS ST VANCOUVER, V6B1A8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 406 - 969 RICHARDS ST, BUZZER 0456 LINDSAY: 778.873.3106 *CANNOT COME EARLIER VANCOUVER, V6B1A8 BRITISH COLUMBIA, CANADA	
PHONE 778.772.7336		EMAIL maxinejakubke@gmail.com	

REASON FOR TODAY'S CALL:  
 My sink: the garburator has stopped working and the sink water takes a long time to go down.

DESCRIPTION OF WORK PERFORMED:  
 I unjammed the garburator and tested by filling and draining the sink while running the garburator. Nothing was pulled out of the grinding chamber, whatever caused it to seize up was flushed through.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
SUBTOTAL:				\$109.00
GST (5%):				\$5.45
TOTAL:				\$114.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-09-28

CUSTOMER SIGNATURE

DATE