



HST #837181627

DATE 2016-10-11	TECHNICIAN Darren Mann		JOB/OF 6591	RDER #	REFERENCE TEXT Client reference
FIRST NAME Talita		LAST NAME Kallie	97		
BILLING ADDRESS COMPANY / BILLING NAME 908 - 933 HORNBY ST VANCOUVER, V6Z 3G4 BRITISH COLUMBIA, CANADA	4		4	SERVICE ADDRESS 908 - 933 HORNBY STREET BUZZER: 2019 VANCOUVER, V6Z 3G4 BRITISH COLUMBIA, CANADA	
PHONE 778.214.6814				EMAIL tikallie@hotmail.com	

REASON FOR TODAY'S CALL: Both bathtub drains are clogged.

<u>Thank You!</u>

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from both bathtubs and tested by filling the tubs 8" and draining

CHARGES. E. & O. E.

QTY.	CODE		DESCRIPTION			
1		Clean drain using PowerSpir	Clean drain using PowerSpin / Tub/Shower			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		WARRANTY	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$149.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45	
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45	
		we did. MADE THE MATERIAL SETTLED.	AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ATT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND SELISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, RUSTED, DETERIORATION, OR LEAD PIPPS, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES OF FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.			

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2016-10-11

DATE