



DATE 2016-10-18	TECHNICIAN Darren Mann	JOB/ORDER # 6614	REFERENCE TEXT Client reference
FIRST NAME ShinYoung		LAST NAME Kim	
BILLING ADDRESS COMPANY / BILLING NAME 2301 - 788 HAMILTON ST VANCOUVER, V6B 0E9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2301 - 788 HAMILTON ST BUZZER: 6213 VANCOUVER, V6B 0E9 BRITISH COLUMBIA, CANADA	
PHONE 604.781.6348		EMAIL namhawun13@gmail.com	

REASON FOR TODAY'S CALL:
 -non-stop hissing noise -water supply is not well

DESCRIPTION OF WORK PERFORMED:
 The FillValve was malfunctioning, not stopping the flow of water when the tank was full causing water to constantly flow into the overflow tube and through the bowl. I replaced the FillValve and supply line and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$149.00	\$149.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$149.00
GST (5%):	\$7.45
TOTAL:	\$156.45

_____ 2016-10-18

 CUSTOMER SIGNATURE DATE