

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2016-10-27	TECHNICIAN Darren Mann		JOB/OI 6645	RDER #	REFERENCE TEXT Client reference
FIRST NAME Krystie		LAST NAME Babalos	7		
BILLING ADDRESS COMPANY / BILLING NAME 418 - 1333 HORNBY ST VANCOUVER, V6V2C1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 418 - 1333 HORNBY STREET ROSIE: 778.233.9672 VANCOUVER, V6V2C1 BRITISH COLUMBIA, CANADA	
PHONE 604.838.0317				EMAIL krystiebab@hotmail.com	

REASON FOR TODAY'S CALL: The shower drain is clogged

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clean the tub drain and tested by filling the tub 8" and draining.

TECHNICIAN RECOMMENDATIONS:

*It was mentioned while onsite that the tub would back up with dirty water even when no fixtures were being used within the apartment. If this happens again in the future I would strongly suggest mentioning this to the building manager right away as this is usually a sign that there is a blockage or congestion within the buildings main drainage stack.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE	
1	1 Clean drain using PowerSpin / Tub/Shower				
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS 30 DAYS ON REPAIR VOID AFTER 30 DAYS IF	GST (5%):	\$7.45	
		.com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45	
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,			
		2016-10-27			
		CUSTOMER SIGNATURE DATE			