



HST #837181627

DATE 2016-10-28	TECHNICIAN Darren Mann		JOB/ORDER # 6644		REFERENCE TEXT Client reference
FIRST NAME Laura		LAST NAME Brain	97		
BILLING ADDRESS COMPANY / BILLING NAME 1749 MAPLE ST VANCOUVER, V6J3S5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 1749 MAPLE ST VANCOUVER, V6J3S5 BRITISH COLUMBIA, CANADA	
PHONE 604.360.2585				EMAIL laurajhume@yahoo.com	

REASON FOR TODAY'S CALL:

Leaking shower(Tempress ii). Leaking U-bend under bathroom sink.

DESCRIPTION OF WORK PERFORMED:

-I replaced the cartridge within the master bathroom shower valve and tested. -The leak under the sink was coming from the connection between the sink and the mechanical drain assembly, I tightened the nut securing the mechanical drain pop-up assembly in the left lavatory sink(master) and tested by filling and draining the

QTY.	CODE	DESCRIPTION				PRICE
1		Replace Shower C	\$199.00	\$199.00		
0	Gwe us Feedback WARRANTY:		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		•	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$208.95	
		MADE THAT MATERIALS	T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES			

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

<u> Thank You!</u>

CUSTOMER SIGNATURE DATE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK