



HST #837181627

DATE 2016-11-08	TECHNICIAN Darren Mann		JOB/ORDER # 6687		REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin			
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 1907 - 909 MAINLAND ST BUZ#6170 PAUL: 604.671.4977 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:

-garburator jammed. -shower head spraying water unevenly.

DESCRIPTION OF WORK PERFORMED:

-The garburator grinding chamber was seized up due to rust and had deteriorated to the point that it could not be repaired. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator. -I replaced the faulty shower head with new and tested.

QII.	CODE	DESCRIPTION	ONIT PRICE	FRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator		\$279.00
1	11	Delta Shower Head	\$15.00	\$15.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$294.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$14.70
			TOTAL:	\$308.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW! MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THA MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESP SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AN RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	IT CHARGES AND ONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER	RIALS AND TRUCK
CHARGES. E. & O. E.	
	2016-11-08
CUSTOMER SIGNATURE	DATE