

Phone: 604.727.4484 yaletownplumbing.com



2016-09-16

HST #837181627

DATE 2016-09-16	TECHNICIAN Darren Mann		JOB/O 6507	RDER #	REFERENCE TEXT Client reference
FIRST NAME Peter		LAST NAME Waignein	97		
BILLING ADDRESS COMPANY / BILLING NAME 3025 BIRCH ST VANCOUVER, V6H2T8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  3025 BIRCH ST VANCOUVER, V6H2T8 BRITISH COLUMBIA, CANADA	
PHONE 604.512.2355				EMAIL peterwaignein@gmail.com	

## REASON FOR TODAY'S CALL:

master bathroom shower won't fully shut off.

## DESCRIPTION OF WORK PERFORMED:

---Sep16: I removed the shower valve trim and found that the valve used is a high flow valve that requires a special order cartridge. I contacted Kohler and they agreed to send out a replacement under warranty. ---Nov2: I installed the new cartridge(GP1144925). During testing I noticed a small leak from the valve mixing cover. I removed it and couldn't find anything visually wrong with it, re-installed it but the leak persisted. I drove to a local Kohler re-seller and bought a valve kit, removed the cover and installed it. Tested and no leak present. I will contact Kohler and have them send out a new valve cover and return the one I purchased.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
2.5	//.	Discount Labour	\$99.00	\$247.50
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$12.38
		s from your	TOTAL:	\$259.88
		ve did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		