

HST #837181627

DATE 2016-11-09	TECHNICIAN Darren Mann		JOB/ORDER # 6683	REFERENCE TEXT Client reference	
FIRST NAME Salome		LAST NAME Homeyer			
BILLING ADDRESS COMPANY / BILLING NAME 206 - 1425 WEST 6TH AVE VANCOUVER, V6H 4G5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS  206 - 1425 WEST 6TH AVE BUZZER: 027 VANCOUVER, V6H 4G5 BRITISH COLUMBIA, CANADA			
PHONE 604.961.1696			EMAIL salome@deltalanddev	EMAIL salome@deltalanddev.com	

## REASON FOR TODAY'S CALL:

Toilet isn't flushing properly - not a lot of water comes back after a flush.

## DESCRIPTION OF WORK PERFORMED:

The FillValve was not functioning properly, not allowing enough water into the tank and bowl after each flush, and the flapper was starting to warp. I replaced the FillValve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard			\$169.00
		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$177.45
			AT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u>Thank You!</u>

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

CUSTOMER SIGNATURE

DATE