



2016-11-14

HST #837181627

DATE 2016-11-14	TECHNICIAN Darren Mann		JOB/ORDER # 6699	REFERENCE TEXT Client reference
FIRST NAME Rita		LAST NAME Lau		
BILLING ADDRESS COMPANY / BILLING NAME 844 WEST 6TH AVE VANCOUVER, V5Z 1A6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 844 W 6TH AVE. BUZ#1162 WE'RE IN THE INSIDE LAST UNIT ON THE LEFT. VANCOUVER, V5Z 1A6 BRITISH COLUMBIA, CANADA	
PHONE 604.782.0987			EMAIL ritamak7@gmail.com	7×/

REASON FOR TODAY'S CALL:

When the garburator is off, the drainage is slow as compared to previously. When garburator switched is turned on, there is no sound and there is no change in the drain speed.

DESCRIPTION OF WORK PERFORMED:

-I unjammed the garburator and tested by filling and draining the sink multiple times. I was not able to find anything out of the ordinary inside the garburator, whatever caused the garburator to jam up was pushed through.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	//	Labour			\$109.00	\$109.00
<i>Q</i>	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY					\$109.00
	Gwe us Feedback Please visit our feedback page at:		C	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45	
		MADE THAT S MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			